Oil Field Environmental Incident Summary

Incident: 20140710164337 **Date/Time of Notice:** 07/10/2014 16:43 Responsible Party: QC ENVIRONMENTAL SERVICES, INC. QC ENVIRONMENTAL SERVICES, INC. Well Name: EIDSVOOG 1-28H Field Name: CHURCH Well File #: 11216 Date Incident: 7/10/2014 Time Incident: 01:00 Facility ID Number: **WILLIAMS Twp:** 158 Rna: 100 Sec: 28 Qtr: County: Location Description: Submitted By: Luke Wolf Received By: Contact Person: Lincoln Finnesgaard 10454 1 S STREET SW KILLDEER, ND 58640 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Valve/Piping Connection Leak Release Contained in Dike: Yes - Within Dike Reported to NRC: Unknown Units Spilled Recovered Units Followup **Units** Oil **Brine** 12 **Barrels** 10 Barrels Other **Description of Other Released Contaminant:**

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

none

Potential Environmental Impacts:

none

Action Taken or Planned:

Spill is contained within containment diking. Vacuum Truck has sucked up all the brine water within dike and absorbent has been placed on ground. More absorbent will be added if necessary. Roustabout crew to replace malfunctioned Flange/Fitting immediately.

Wastes Disposal Location: The Vacuum Truck unloaded recovered brine back into disposal facility.

Agencies Involved:

Updates

Date: 7/10/2014 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.